

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L11	0	(retrievable while drilling tool communication coupler sensor pressure).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:48
L12	0	(retrievable while drilling tool communication coupler sensor pressure).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	AND	ON	2006/09/29 10:46
L13	0	(retrievable while drilling tool communication coupler sensor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:46
L14	0	(retrievable while drilling tool coupler sensor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:46
L15	0	(retrievable while drilling tool).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:47
L16	17	(retrievable drilling tool).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:47
L17	0	(land collar while drilling tool communication pocket sensor).clm.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:49

EAST Search History

L18	0	(landing collar while drilling tool communication pocket sensor).clm.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:49
L19	1	(landing collar drilling tool communication pocket sensor).clm.	US_PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	SAME	ON	2006/09/29 10:49